

## Monroe Technical Note 65

Not suited for the replacement of the Hi-Riser in vehicles with Leveling Suspension.