


MONROE

Technical Notes

TECHNICAL NOTES FROM THE LEADERS IN RIDE PERFORMANCE



Monroe Technical Note

115

If the O.E. camber adjustment screw is seized or rusted, remove the screw & fit MC114 Magic Camber bolt.



Monroe Technical Helpline
1800 088 205

www.monroe.com.au